Printing date 10/03/2018

Reviewed on 10/03/2018

# **1** Identification


- · Product identifier
- Trade name: <u>Color Reagent</u> Hach EZ 2306 Analyzer
- · Article number: ND580
- Details of the supplier of the safety data sheet
  Manufacturer/Supplier: Aqua Solutions, Inc.
  6913 Highway 225 DEER PARK, TX 77536 USA

800-256-2586

- Information department: Technical Coordinator Sherman Nelson sherman@aquasolutions.org
   Emergency telephone number:
- *Chemtrec:* 800-424-9300 *Canutec:* 613-996-6666

# **2** *Hazard*(*s*) *identification*

· Classification of the substance or mixture



Skin Corr. 1A H314 Causes severe skin burns and eye damage.

Eye Dam. 1 H318 Causes serious eye damage.

· Label elements

• *GHS label elements* The product is classified and labeled according to the Globally Harmonized System (GHS). • *Hazard pictograms* 



## · Signal word Danger

· Hazard statements

Causes severe skin burns and eye damage.

· Precautionary statements

Do not breathe dusts or mists.

Wash thoroughly after handling.

- Wear protective gloves/protective clothing/eye protection/face protection.
- If swallowed: Rinse mouth. Do NOT induce vomiting.
- If on skin (or hair): Take off immediately all contaminated clothing. Rinse skin with water/shower.
- IF INHALED: Remove person to fresh air and keep comfortable for breathing.

If in eyes: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.

Immediately call a poison center/doctor.

Specific treatment (see on this label).

Wash contaminated clothing before reuse.

Store locked up.

(Contd. on page 2)


US



Printing date 10/03/2018

Reviewed on 10/03/2018

Trade name: Color Reagent Hach EZ 2306 Analyzer



· Dangerous components: Not Applicable

• Table of Nonhazardous Ingredients
 CAS: 7647-01-0 Hydrochloric Acid

CAS: 3682-35-7 2,4,6-tris(2-pyridyl)-s-triazine

CAS: 7732-18-5 Water

# 4 First-aid measures

- · Description of first aid measures
- · General information: Immediately remove any clothing soiled by the product.
- After inhalation: In case of unconsciousness place patient stably in side position for transportation.
- · After skin contact: Immediately wash with water and soap and rinse thoroughly.
- After eye contact: Rinse opened eye for several minutes under running water. Then consult a doctor.
- After swallowing: Drink copious amounts of water and provide fresh air. Immediately call a doctor.
- Information for doctor:
- · Most important symptoms and effects, both acute and delayed No further relevant information available.
- · Indication of any immediate medical attention and special treatment needed

No further relevant information available.

# **5** Fire-fighting measures

- · Extinguishing media
- Suitable extinguishing agents: Use fire fighting measures that suit the environment.
- $\cdot$  Special hazards arising from the substance or mixture
- During heating or in case of fire poisonous gases are produced.

(Contd. on page 3)

0.83%

0.075%

99.095%

US

Printing date 10/03/2018

Reviewed on 10/03/2018

Trade name: Color Reagent Hach EZ 2306 Analyzer

Huch EL 2500 Analyze

· Advice for firefighters

· Protective equipment: Mouth respiratory protective device.

# 6 Accidental release measures

· Personal precautions, protective equipment and emergency procedures Mount respiratory protective device. Wear protective equipment. Keep unprotected persons away. • *Environmental precautions:* Dilute with plenty of water. • Methods and material for containment and cleaning up: Absorb with liquid-binding material (sand, diatomite, acid binders, universal binders, sawdust). Use neutralizing agent. Dispose contaminated material as waste according to item 13. Ensure adequate ventilation. · Reference to other sections See Section 7 for information on safe handling. See Section 8 for information on personal protection equipment. See Section 13 for disposal information. · Protective Action Criteria for Chemicals · PAC-1: CAS: 7647-01-0 Hydrochloric Acid · PAC-2: CAS: 7647-01-0 Hydrochloric Acid

· PAC-3:

CAS: 7647-01-0 Hydrochloric Acid

# 7 Handling and storage

· Handling:

• **Precautions for safe handling** Ensure good ventilation/exhaustion at the workplace. Prevent formation of aerosols.

• Information about protection against explosions and fires: Keep respiratory protective device available.

· Conditions for safe storage, including any incompatibilities

· Storage:

- · Requirements to be met by storerooms and receptacles: No special requirements.
- · Information about storage in one common storage facility: Not required.
- Further information about storage conditions: Keep receptacle tightly sealed.
- · Specific end use(s) No further relevant information available.

## 8 Exposure controls/personal protection

• Additional information about design of technical systems: No further data; see item 7.

· Control parameters

· Components with limit values that require monitoring at the workplace:

The product does not contain any relevant quantities of materials with critical values that have to be monitored at the workplace.

(Contd. on page 4)

(Contd. of page 2)

1.8 ppm

22 ppm

100 ppm

US

Printing date 10/03/2018

Reviewed on 10/03/2018

Trade name: Color Reagent Hach EZ 2306 Analyzer

Seposure controls Personal protective equipment: General protective and hygienic measures: Keep away from foodstuffs, beverages and feed. mmediately remove all soiled and contaminated clothing. Wash hands before breaks and at the end of work. Woid contact with the eyes. Noid contact with the eyes and skin. Breathing equipment: n case of brief exposure or low pollution use respiratory filter device. In case of intensive or longer exposure use respiratory protective device that is independent of circulating air. Protection of hands: The glove material has to be impermeable and resistant to the product/ the substance/ the preparation. Due to missing tests no recommendation to the glove material can be given for the product/ the preparation. Due to missing tests no recommendation of the penetration times, rates of diffusion and the degradation Material of gloves The glove material on consideration of the penetration times, rates of diffusion and the degradation Material of gloves The selection of the suitable gloves does not only depend on the material, but also on further marks of quality a varies from manufacturer to manufacturer. As the product is a preparation of several substances, the resistance he glove material can not be calculated in advance and has therefore to be checked prior to the application. Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to beserved. Step rotection: Tightly sealed goggles	Additional information. The lists that were valid during the exection were used as basis	(Contd. of page
Personal protective equipment: General protective and hygienic measures: Keep away from foodstuffs, beverages and feed. mmediately remove all soiled and contaminated clothing. Wash hands before breaks and at the end of work. Woid contact with the eyes. Woid contact with the eyes. Reaching equipment: n case of brief exposure or low pollution use respiratory filter device. In case of intensive or longer exposure us expiratory protective device that is independent of circulating air. Protection of hands: Protective gloves Free glove material has to be impermeable and resistant to the product/ the substance/ the preparation. Due to missing tests no recommendation to the glove material can be given for the product/ the preparation. Bue to missing tests no recommendation of the penetration times, rates of diffusion and the degradation Material of gloves The selection of the suitable gloves does not only depend on the material, but also on further marks of quality a rairies from manufacturer to manufacturer. As the product is a preparation of several substances, the resistance he glove material can not be calculated in advance and has therefore to be checked prior to the application. Penetration time of glove material File exact break through time has to be found out by the manufacturer of the protective gloves and has to observed. Expertences: Expertences: Tightly sealed goggles Bady protection: Protective work clothing	Additional information: The lists that were valid during the creation were used as basis.	
General protective and hygienic measures:         Case away from foodstuffs, beverages and feed.         mmediately remove all solled and contaminated clothing.         Vash hands before breaks and at the end of work.         Void contact with the eyes.         Wood contact with the eyes and skin.         Streathing equipment:         n case of brief exposure or low pollution use respiratory filter device. In case of intensive or longer exposure usespiratory protective device that is independent of circulating air.         Protection of hands:         Image: the glove material has to be impermeable and resistant to the product/ the substance/ the preparation.         Due to missing tests no recommendation to the glove material can be given for the product/ the preparation/ the the existent to the product of the glove material on consideration of the penetration times, rates of diffusion and the degradation that the slow anterial of gloves         The selection of the suitable gloves does not only depend on the material, but also on further marks of quality a arise from manufacturer to manufacturer. As the product is a preparation of several substances, the resistance he glove material can not be calculated in advance and has therefore to be checked prior to the application.         Penetration fine of glove material       mutdature.         Protection of the suitable gloves does not only depend on the material, but also on further marks of quality a arise from manufacturer to manufacturer. As the product is a preparation of several substances, the resistance he glove material can not be calculated in advance and has therefore to be checked		
<ul> <li>Keep away from foodstuffs, beverages and feed.</li> <li>mmediately remove all soiled and contaminated clothing.</li> <li>Wash hands before breaks and at the end of work.</li> <li>Woid contact with the eyes.</li> <li>Woid contact with the eyes and skin.</li> <li><b>Fraching equipment:</b></li> <li>n case of brief exposure or low pollution use respiratory filter device. In case of intensive or longer exposure a expiratory protective device that is independent of circulating air.</li> <li><b>Protection of hands:</b></li> <li><b>Protective gloves</b></li> <li><b>Protective gloves</b></li> <li><b>Protective gloves</b></li> <li><b>Protection of the glove material has to be impermeable and resistant to the product/ the substance/ the preparation.</b></li> <li><b>Due to missing tests no recommendation to the glove material can be given for the product/ the preparation.</b></li> <li><b>Due to missing tests no recommendation of the penetration times, rates of diffusion and the degradation Material of gloves</b></li> <li><b>The selection of the substance of the antipacturer.</b> As the product is a preparation of several substances, the resistance he glove material can not be calculated in advance and has therefore to be checked prior to the application.</li> <li><b>Penetation time of glove material</b></li> <li><b>Penetation:</b></li> <li><b>Penetation:</b></li> <li><b>Penetation:</b></li> <li><b>Penetation:</b></li> <li><b>Tightly sealed goggles</b></li> <li><b>Bady protection:</b> Protective work clothing</li> </ul>		
<ul> <li>mmediately remove all soiled and contaminated clothing.</li> <li>Wash hands before breaks and at the end of work.</li> <li>Woold contact with the eyes.</li> <li>Woold contact with the eyes and skin.</li> <li>Breathing equipment: <ul> <li>n case of brief exposure or low pollution use respiratory filter device. In case of intensive or longer exposure a respiratory protective device that is independent of circulating air.</li> </ul> </li> <li>Protection of hands: <ul> <li>Protective gloves</li> </ul> </li> <li>Protective glove material has to be impermeable and resistant to the product/ the substance/ the preparation.</li> <li>Due to missing tests no recommendation to the glove material can be given for the product/ the preparation / themical mixture.</li> <li>Selection of the suitable gloves does not only depend on the material, but also on further marks of quality a varies from manufacturer to manufacturer. As the product is a preparation of several substances, the resistance he glove material can not be calculated in advance and has therefore to be checked prior to the application.</li> <li>Pretection:</li> <li>Protection:</li> <li>Protection:</li> <li>Protection:</li> </ul>		
<ul> <li>Wash hands before breaks and at the end of work.</li> <li>Woid contact with the eyes.</li> <li>Woid contact with the eyes and skin.</li> <li>Breathing equipment:</li> <li>In case of brief exposure or low pollution use respiratory filter device. In case of intensive or longer exposure of exposure or protective device that is independent of circulating air.</li> <li>Protection of hands:</li> <li>Protective gloves</li> <li>The glove material has to be impermeable and resistant to the product/ the substance/ the preparation/ to the minimum deterior of the glove material on consideration of the glove material can be given for the product/ the preparation of the degradation to the glove material of gloves</li> <li>The selection of the suitable gloves does not only depend on the material, but also on further marks of quality a varies from manufacturer to manufacturer. As the product is a preparation of several substances, the resistance he glove material can not be calculated in advance and has therefore to be checked prior to the application.</li> <li>Penetration time of glove material</li> <li>Potection:</li> <li>Protection:</li> <li>Tightly sealed goggles</li> </ul>		
Avoid contact with the eyes. Avoid contact with the eyes and skin. Breathing equipment: n case of brief exposure or low pollution use respiratory filter device. In case of intensive or longer exposure and expiratory protective device that is independent of circulating air. Protection of hands: Protection of hands: Protective gloves Fhe glove material has to be impermeable and resistant to the product/ the substance/ the preparation. Due to missing tests no recommendation to the glove material can be given for the product/ the preparation/ to themical mixture. Selection of the glove material on consideration of the penetration times, rates of diffusion and the degradation Material of gloves The selection of the suitable gloves does not only depend on the material, but also on further marks of quality and varies from manufacturer to manufacturer. As the product is a preparation of several substances, the resistance he glove material can not be calculated in advance and has therefore to be checked prior to the application. Protection: Protec		
Avoid contact with the eyes and skin. Breathing equipment: In case of brief exposure or low pollution use respiratory filter device. In case of intensive or longer exposure or respiratory protective device that is independent of circulating air. Protection of hands: The glove material has to be impermeable and resistant to the product/ the substance/ the preparation. Due to missing tests no recommendation to the glove material can be given for the product/ the preparation/ the themical mixture. Selection of the gloves material on consideration of the penetration times, rates of diffusion and the degradation Material of gloves The selection of the substance to manufacturer. As the product is a preparation of several substances, the resistance he glove material can not be calculated in advance and has therefore to be checked prior to the application. Penetration time of glove material the exact break through time has to be found out by the manufacturer of the protective gloves and has to observed. By protection: Tightly sealed goggles Body protection: Protective work clothing		
<ul> <li>Breathing equipment:</li> <li>In case of brief exposure or low pollution use respiratory filter device. In case of intensive or longer exposure or exposure or lessing to the exposure of the exposur</li></ul>		
in case of brief exposure or low pollution use respiratory filter device. In case of intensive or longer exposure use privatory protective device that is independent of circulating air. Protection of hands: Protective gloves The glove material has to be impermeable and resistant to the product/ the substance/ the preparation. Due to missing tests no recommendation to the glove material can be given for the product/ the preparation/ the themical mixture. Selection of the suitable gloves does not only depend on the material, but also on further marks of quality a varies from manufacturer to manufacturer. As the product is a preparation of several substances, the resistance he glove material can not be calculated in advance and has therefore to be checked prior to the application. Pretection time of glove material For exact break through time has to be found out by the manufacturer of the protective gloves and has to be beserved. Experimental goggles Body protection: Protective work clothing		
espiratory protective device that is independent of circulating air. Protection of hands: Protection of hands: Protective gloves The glove material has to be impermeable and resistant to the product/ the substance/ the preparation. Due to missing tests no recommendation to the glove material can be given for the product/ the preparation/ the hemical mixture. Selection of the glove material on consideration of the penetration times, rates of diffusion and the degradation Material of gloves The selection of the suitable gloves does not only depend on the material, but also on further marks of quality a varies from manufacturer to manufacturer. As the product is a preparation of several substances, the resistance he glove material can not be calculated in advance and has therefore to be checked prior to the application. Penetration time of glove material Fhe exact break through time has to be found out by the manufacturer of the protective gloves and has to observed. Eye protection: Tightly sealed goggles Body protection: Protective work clothing		onger exposure u
Protection of hands: Protective gloves Free glove material has to be impermeable and resistant to the product/ the substance/ the preparation. Due to missing tests no recommendation to the glove material can be given for the product/ the preparation/ t hemical mixture. Selection of the glove material on consideration of the penetration times, rates of diffusion and the degradation Material of gloves The selection of the suitable gloves does not only depend on the material, but also on further marks of quality a varies from manufacturer to manufacturer. As the product is a preparation of several substances, the resistance he glove material can not be calculated in advance and has therefore to be checked prior to the application. Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to observed. Eye protection: Tightly sealed goggles Body protection: Protective work clothing		onger exposure u
Protective gloves Fhe glove material has to be impermeable and resistant to the product/ the substance/ the preparation. Due to missing tests no recommendation to the glove material can be given for the product/ the preparation/ the themical mixture. Selection of the glove material on consideration of the penetration times, rates of diffusion and the degradation Material of gloves The selection of the suitable gloves does not only depend on the material, but also on further marks of quality and varies from manufacturer to manufacturer. As the product is a preparation of several substances, the resistance the glove material can not be calculated in advance and has therefore to be checked prior to the application. Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to observed. Eye protection: Tightly sealed goggles Body protection: Protective work clothing		
Due to missing tests no recommendation to the glove material can be given for the product/ the preparation/ the chemical mixture. Selection of the glove material on consideration of the penetration times, rates of diffusion and the degradation <b>Material of gloves</b> The selection of the suitable gloves does not only depend on the material, but also on further marks of quality a paries from manufacturer to manufacturer. As the product is a preparation of several substances, the resistance the glove material can not be calculated in advance and has therefore to be checked prior to the application. Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to observed. Eye protection: Tightly sealed goggles Body protection: Protective work clothing	Protective gloves	
Due to missing tests no recommendation to the glove material can be given for the product/ the preparation/ the chemical mixture. Selection of the glove material on consideration of the penetration times, rates of diffusion and the degradation <b>Material of gloves</b> The selection of the suitable gloves does not only depend on the material, but also on further marks of quality a paries from manufacturer to manufacturer. As the product is a preparation of several substances, the resistance the glove material can not be calculated in advance and has therefore to be checked prior to the application. Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to observed. Eye protection: Tightly sealed goggles Body protection: Protective work clothing	The glove material has to be impermeable and resistant to the product/ the substance/ the preparet	aration.
<ul> <li>Material of gloves</li> <li>The selection of the suitable gloves does not only depend on the material, but also on further marks of quality are paraies from manufacturer to manufacturer. As the product is a preparation of several substances, the resistance he glove material can not be calculated in advance and has therefore to be checked prior to the application.</li> <li>Penetration time of glove material</li> <li>The exact break through time has to be found out by the manufacturer of the protective gloves and has to observed.</li> <li>Eye protection:</li> <li>Tightly sealed goggles</li> <li>Body protection: Protective work clothing</li> </ul>		
The selection of the suitable gloves does not only depend on the material, but also on further marks of quality a varies from manufacturer to manufacturer. As the product is a preparation of several substances, the resistance he glove material can not be calculated in advance and has therefore to be checked prior to the application. Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to observed. Eye protection: Tightly sealed goggles Body protection: Protective work clothing		the degradation
Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to observed. Eye protection: Tightly sealed goggles Body protection: Protective work clothing	The selection of the suitable gloves does not only depend on the material, but also on further n varies from manufacturer to manufacturer. As the product is a preparation of several substance	es, the resistance
The exact break through time has to be found out by the manufacturer of the protective gloves and has to observed. Eye protection: Tightly sealed goggles Body protection: Protective work clothing		e application.
observed. Eye protection: Tightly sealed goggles Body protection: Protective work clothing		oves and has to
Eye protection: Tightly sealed goggles Body protection: Protective work clothing	observed.	5705 and has 10
Tightly sealed goggles Body protection: Protective work clothing	Eye protection:	
	Tightly sealed goggles	
Physical and chemical properties	Body protection: Protective work clothing	
	Physical and chemical properties	

· Information on basic physical and chemical properties	
· General Information	

•	General	Inj	form	atio
	Annoard	1100	<b></b>	

· Appearance:		
Form:	Liquid	
Color:	Colorless	
· Odor:	Odorless	
• Odor threshold:	Not determined.	
· pH-value at 20 •C (68 •F):	<2	
· Change in condition		
Melting point/Melting range:	0 °C (32 °F)	
Boiling point/Boiling range:	100 °C (212 °F)	
		(Contd. on page 5)
		(Contd.

Printing date 10/03/2018

Reviewed on 10/03/2018

#### Trade name: Color Reagent Hach EZ 2306 Analyzer

	(Contd. of pa	age 4
· Flash point:	Not applicable.	
· Flammability (solid, gaseous):	Not applicable.	
· Decomposition temperature:	Not determined.	
· Auto igniting:	Product is not selfigniting.	
· Danger of explosion:	Product does not present an explosion hazard.	
· Explosion limits:		
Lower:	Not determined.	
Upper:	Not determined.	
· Vapor pressure at 20 °C (68 °F):	23 hPa (17.3 mm Hg)	
· Density:	Not determined.	
· Relative density	Not determined.	
· Vapor density	Not determined.	
$\cdot$ Evaporation rate	Not determined.	
· Solubility in / Miscibility with		
Water:	Fully miscible.	
· Partition coefficient (n-octanol/wate	e <b>r):</b> Not determined.	
· Viscosity:		
Dynamic:	Not determined.	
Kinematic:	Not determined.	
· Solvent content:		
Water:	99.1 %	
VOC content:	0.00 %	
	0.0 g/l / 0.00 lb/gal	
Solids content:	0.1 %	
• Other information	No further relevant information available.	

# **10 Stability and reactivity**

· **Reactivity** No further relevant information available.

- · Chemical stability
- Thermal decomposition / conditions to be avoided: No decomposition if used according to specifications.
- · Possibility of hazardous reactions No dangerous reactions known.
- · Conditions to avoid No further relevant information available.
- · Incompatible materials: No further relevant information available.
- · Hazardous decomposition products: No dangerous decomposition products known.

# **11 Toxicological information**

- · Information on toxicological effects
- · Acute toxicity:
- Primary irritant effect:
- on the skin: Strong caustic effect on skin and mucous membranes.
- $\cdot$  on the eye:
- Strong caustic effect.

(Contd. on page 6)

US -

*Printing date 10/03/2018* 

Reviewed on 10/03/2018

## Trade name: Color Reagent Hach EZ 2306 Analyzer

(Contd. of page 5)

Strong irritant with the danger of severe eye injury.

• Sensitization: No sensitizing effects known.

· Additional toxicological information:

The product shows the following dangers according to internally approved calculation methods for preparations: Corrosive

Irritant

Swallowing will lead to a strong caustic effect on mouth and throat and to the danger of perforation of esophagus and stomach.

· Carcinogenic categories

· IARC (International Agency for Research on Cancer)

None of the ingredients is listed.

· NTP (National Toxicology Program)

None of the ingredients is listed.

#### · OSHA-Ca (Occupational Safety & Health Administration)

None of the ingredients is listed.

# **12 Ecological information**

#### · Toxicity

- Aquatic toxicity: No further relevant information available.
- · Persistence and degradability No further relevant information available.
- · Behavior in environmental systems:
- · Bioaccumulative potential No further relevant information available.
- *Mobility in soil* No further relevant information available.
- Additional ecological information:
- · General notes:
- Generally not hazardous for water

Must not reach bodies of water or drainage ditch undiluted or unneutralized.

Rinse off of bigger amounts into drains or the aquatic environment may lead to decreased pH-values. A low pH-value harms aquatic organisms. In the dilution of the use-level the pH-value is considerably increased, so that after the use of the product the aqueous waste, emptied into drains, is only low water-dangerous.

- · Results of PBT and vPvB assessment
- · **PBT:** Not applicable.
- vPvB: Not applicable.
- · Other adverse effects No further relevant information available.

# **13 Disposal considerations**

- · Waste treatment methods
- · Recommendation:

Must not be disposed of together with household garbage. Do not allow product to reach sewage system.

- · Uncleaned packagings:
- Recommendation: Disposal must be made according to official regulations.
- · Recommended cleansing agent: Water, if necessary with cleansing agents.

(Contd. on page 7)

Printing date 10/03/2018

Reviewed on 10/03/2018

# Trade name: Color Reagent

Hach EZ 2306 Analyzer

(Contd. of page 6)

· UN-Number · DOT, IMDG, IATA	Not regulated	
· UN proper shipping name · DOT, IMDG, IATA	Not regulated	
· Transport hazard class(es)		
· DOT, IMDG, IATA		
· Class	Not regulated	
· Packing group		
· DOT, IMDG, IATA	Not regulated	
· Environmental hazards:	Not applicable.	
· Special precautions for user	Not applicable.	
· Transport in bulk according to Annex	II of	
MARPOL73/78 and the IBC Code	Not applicable.	

# **15 Regulatory information**

 $\cdot$  Safety, health and environmental regulations/legislation specific for the substance or mixture  $\cdot$  Sara

· Section 355 (extremely hazardous substances):

None of the ingredients is listed.

· Section 313 (Specific toxic chemical listings):

None of the ingredients is listed.

· TSCA (Toxic Substances Control Act):

Hydrochloric Acid

2,4,6-tris(2-pyridyl)-s-triazine

Water

## · Proposition 65

· Chemicals known to cause cancer:

None of the ingredients is listed.

· Chemicals known to cause reproductive toxicity for females:

None of the ingredients is listed.

· Chemicals known to cause reproductive toxicity for males:

None of the ingredients is listed.

· Chemicals known to cause developmental toxicity:

None of the ingredients is listed.

· Carcinogenic categories

· EPA (Environmental Protection Agency)

None of the ingredients is listed.

(Contd. on page 8)

US

Printing date 10/03/2018

Reviewed on 10/03/2018

Trade name: Color Reagent

Hach EZ 2306 Analyzer

• TLV (Threshold Limit Value established by ACGIH)

(Contd. of page 7)

Ν	NOSH-Ca (National Institute for Occupational Safety and Health)
Ν	lone of the ingredients is listed.
(	GHS label elements The product is classified and labeled according to the Globally Harmonized System (GHS)
ŀ	Iazard pictograms
	<b>∧</b>
	EG
1	
	GHS05
S	ignal word Danger
	Iazard statements
	Causes severe skin burns and eye damage.
	Precautionary statements
	Do not breathe dusts or mists.
V	Vash thoroughly after handling.
	Vear protective gloves/protective clothing/eye protection/face protection.
	f swallowed: Rinse mouth. Do NOT induce vomiting.
Ĭ	f on skin (or hair): Take off immediately all contaminated clothing. Rinse skin with water/shower.
Ĭ	F INHALED: Remove person to fresh air and keep comfortable for breathing.
I	f in eyes: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to
Ċ	Continue rinsing.
I	mmediately call a poison center/doctor.
S	pecific treatment (see on this label).
V	Vash contaminated clothing before reuse.
S	tore locked up.
L	Dispose of contents/container in accordance with local/regional/national/international regulations.
• (	Chemical safety assessment: A Chemical Safety Assessment has not been carried out.

# **16 Other information**

This information is based on our present knowledge. However, this shall not constitute a guarantee for any specific product features and shall not establish a legally valid contractual relationship.

- · Department issuing SDS: Environment protection department.
- · Contact:
- Date of preparation / last revision Revsion 0.0, 10-03-2018: Creation date for SDS. STN 10/03/2018 / -
- Abbreviations and acronyms:
   ADR: Accord européen sur le transport des marchandises dangereuses par Route (European Agreement concerning the International Carriage of Dangerous Goods by Road)
   IMDG: International Maritime Code for Dangerous Goods
   DOT: US Department of Transportation
   IATA: International Air Transport Association
   ACGIH: American Conference of Governmental Industrial Hygienists
   EINECS: European Inventory of Existing Commercial Chemical Substances
   ELINCS: Chemical Abstracts Service (division of the American Chemical Society)
   NFPA: National Fire Protection Association (USA)
   HMIS: Hazardous Materials Identification System (USA)
   VOC: Volatile Organic Compounds (USA, EU)
   PBT: Persistent, Bioaccumulative and Toxic

(Contd. on page 9)

<sup>-</sup> US

Printing date 10/03/2018

Trade name: Color Reagent Hach EZ 2306 Analyzer Reviewed on 10/03/2018

(Contd. of page 8)

US

vPvB: very Persistent and very Bioaccumulative NIOSH: National Institute for Occupational Safety OSHA: Occupational Safety & Health TLV: Threshold Limit Value PEL: Permissible Exposure Limit REL: Recommended Exposure Limit Skin Corr. 1A: Skin corrosion/irritation – Category 1A Eye Dam. 1: Serious eye damage/eye irritation – Category 1